



NULMAGE

CLEANER & DEBUGGER FOR POLISHED METAL

For cleaning polished skins on aircraft bellies and cowlings, removing oils & fluids without "rainbow effect" left on surface from oil residue.

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.



1. Pour a small amount onto a flannel polishing cloth.
2. Apply to surface, wiping on gently to avoid mechanical scratching from surface soils & dust.
3. Gently spread material over target polish area.
4. Rub until NULMAGE is removed.
5. Slight haze will remain.
6. Allow haze to dry.
7. Continue with the other target polish areas.
8. After haze has dried completely, polish away to bright shine with clean cotton flannel polishing cloth.



STUBBORN BUG REMOVAL

1. Wet bug spot with NULMAGE.
2. Spread material on area around bug while NULMAGE soaks bug material.
3. After a few seconds, rub away bug residue.
4. Keep any remaining bug residue wet & soaking.
5. Remove with gentle rubbing.
6. Repeat until bug spot is disappeared.