



NUPower II

WATERLESS, DRYWASH CLEANER & POLISH with UV PROTECTANT

For Normal or Lightly Oxidized Soiled Surface Conditions

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.



1. Apply NUPower II "AS IS" by hand, with mop head or random orbital.
2. Agitate a small, 18"-24" area* evenly with the product.
3. Allow to dry 5-10 minutes. It will "haze" over.
4. Remove by buffing-out with clean mop head, or dry terry towel, or a clean bonnet head on random orbital.



* THE SHOULDER ZONE

Keep work area same width as shoulders, approximately 18-24".

Plant feet flat on the ground also within the "shoulder" parameter.

Never buff below the belt, meaning no bending to meet lower levels.

Best to be eye level with buffer.