METAL CARE



- **STEP 1:** Apply sparingly with wool compounding pad on circular buffer (1600-2000 rpm).
- **STEP 2:** Polish until oxidation & residue disappear, about 60 seconds.
- **STEP 3:** Repeat if oxidation cloudiness remains.
- **STEP 4:** If swirl marks remain, follow with NUSHINF IIC.
- **STEP 5:** Final finish with NUSHINE IIS with random orbital buffer & cotton.
- **STEP 1:** Apply sparingly with tufted wool compounding pad on circular buffer (1600-2000 rpm).
- **STEP 2:** Polish until oxidation & residue disappear, about 60 seconds.
- **STEP 3:** Final finish with NUSHINE IIS with random orbital buffer & cotton.
- **STEP 1:** Apply sparingly with cotton flannel rag by hand or with orbital-type power polisher (pad faces covered with cotton flannel sheet).
- **STEP 2:** Polish until residue disappears, about 60 seconds.



NUVITE specializes in complete polishing systems. Tell us about your application & we'll put together a set of qualified consumables or have our R&D team develop a customized polishing system unique to your specifications.



Polish Touch-up

- **STEP 1:** Apply "AS IS" (do not dilute) to surface with a clean cotton flannel polishing cloth.
- **STEP 2:** Spread material over target polish area, rub until product is removed, leaving a slight haze on the surface.
- **STEP 3:** When haze dries polish away with a clean cotton flannel polishing cloth.

Debugging/Residue Spot Remover

- STEP 1: Apply "AS IS" (do not dilute) to effected area.
- STEP 2: Spread around effected area & allow to soak.
- STEP 3: Remove with gentle rubbing, until spot dissapears.

INTERIOR CARE



CARPET CLEANER

& SPOT REMOVER

Spot Cleaning

STEP 1: Dilute 1:16 with water. Saturate small area of clean towel and wet spot.

STEP 2: Use dry, clean cloth to soak/blot-out soil. Repeat if necessary.

Hand Cleaning

Clean with up/down, side-to-side action with dry cloth.

Machine Cleaning

Use with rotary type, not for use with steam or extraction machine.



Spot Cleaning

STEP 1: Dilute 1:8 with water in spray bottle. Spray surface, clean with terry towel.

STEP 2: Repeat as necessary.

Broad Area Cleaning:

STEP 1: Clean with up/down, side to side action.

STEP 2: Wipe dry with clean terry towel.



- STEP 1: Pour small amount onto smooth cotton cloth.
- STEP 2: Apply uniformly over surface area.
- STEP 3: Use dry, clean cotton towel to polish to soft luster.



Debugging by Hand

STEP 1: Dilute 1:12 with water. Using trigger spray to wet area.

STEP 2: Wipe with dampened terry towel. Buff to shine with dry towel. No need to rinse.

Wetwash

STEP 1: Dilute 1:10 with water.

STEP 2: Use in pressure system or apply with brush. Rinse.

Degreasing

STEP 1: Apply full strength or dilute 1:4 with water.

STEP 2: Allow to soak. Do not allow to dry. Use high pressure spray to blast away loosened grease. Repeat if necessary.

PAINT CARE GLOSS, POLISH & DRYWASH



*Product dilution determined by extent, condition & soil type.

Wetwash

STEP 1: Dilute 1:8-1:20 with water. Apply with spray, mop, or cloth.

STEP 2: Agitate to loosen soils.

STEP 3: Rinse with water.

Drywash

STEP 1: Dilute 1:8-1:12 with water. Apply with spray or mop/pad.

STEP 2: Agitate to loosen soils.

STEP 3: Wipe with damp, clean towel, frequently turning until surface is dry.

Hand Wash/Wax

STEP 1: Use full strength or up to 1:4 dilution. Apply with spray or mop/pad.

STEP 2: Agitate to loosen soils. Do not allow to dry.

STEP 3: Hand buff dry.



STEP 1: Apply "AS IS" (do not dilute) with towel

STEP 2: Agitate, spreading to very thin layer. Allow to dry.

STEP 3: Hand buff to slick, high shine.



STEP 1: Apply with terry towel or mophead "AS IS" (do not dilute).

STEP 2: Agitate uniformly over surface, spreading material to very thin layer.

STEP 3: Allow to completely dry.

STEP 4: Using clean towel or mophead, hand buff to slick, high gloss.



STEP 1: Pour small amount "AS IS" (do not dilute) onto terry towel.

STEP 2: Apply thinly & uniformly over surface.

STEP 3: Allow to cure until dry.

STEP 4: Hand buff with cotton flannel detailing cloth for extreme gloss.

NUVITE offers a full line of quality products, systems and equipment for Brightwork, Paint Care, Exterior Wash & Interior Care. All NUVITE products have been engineered to meet the most demanding polishing requirements. Count on NUVITE for:

- √ TOP PERFORMANCE
- ✓ EXTRAORDINARY RESULTS
- ✓ EXCEPTIONAL PROTECTION
- ✓ LONGER LASTING SHINE
- ✓ ECO-FRIENDLY
- ✓ USER-FRIENDLY
- ✓ COST-EFFECTIVE

NUVITE Chemical Compounds is a global leader in appearance maintenance chemicals, manufacturing and delivering high quality products for 70 years to aviation/aerospace, automotive, marine, rail, RV & power sports. The NUVITE product line delivers everything you need to achieve that most coveted, sought after, "SHOWROOM SHINE!"

NUVITE is a division of UNIVERSAL PHOTONICS INCORPORATED, manufacturer and global distributor of critical surfacing and polishing materials. UPI's dedication to innovative polishing materials supports NUVITE with state-of-the-art manufacturing facilities and an unwavering commitment to product development.

NUVITE customers can expect fast, dependable service and accurate technical assistance.

Questions? Contact a NUVITE Field Technical Specialist.




WWW.NUVITECHEMICAL.COM





A DIVISION OF UNIVERSAL PHOTONICS INCORPORATED WWW.universalphotonics.com

H2S/1018



BRIGHTWORK
PAINT CARE
INTERIOR CARE

WWW.NUVITECHEMICAL.COM

